

Chief Surveyors 27.3.17

Received from Chief Surveyors

SHIP'S NAME Shells Malmanger

Report Phl

No. 2523

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/02.)

of Survey 1<sup>st</sup> Sub-

When due

100 A-1 (Steel)

"Fitted with cylindrical tanks for carrying petroleum."

1 DK (Steel)

Cell DB 350, 1611E, F.P.T. 115L, A.P.T. 144E

EK 105H avep. P 100i B27 F50 Mchly aft.

M.  
28.3.17

The surveyor should state how the inner surface of the shelf plating in way of the cell double bottom is protected.

5/0. 4/4/17



© 2020

Lloyd's Register Foundation

W839-0016