

total ca,
N.B.—
If the
of the tanks
girders, and

4m,8,15.

WRECK BOX

No.

20 (top).

GOVERNMENT SERVICE.

Received by Chief Ship Surveyor 25. 5. 16

Received from Chief Ship Surveyor

28 MAY 1916

VESSEL'S NAME Stl. S.S. "HUNTSFALL".

Rpt. Nwc.

No. 68763

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey

Con'n Damage

The Algiers' Surveyor reported in April last this vessel had sustained damage to plating through striking Quay wall.

Temporary repairs were effected, and the Surveyor recommended the damaged plating be examined at the next dry docking.

The Newcastle Surveyors now report the vessel has been placed in dry dock, the bottom cleaned, examined & recoated, and the rudder rebushed.

The caulking & riveting in way of five indented shell plates have been overhauled, and the Surveyors recommend the indented plates be faired at Owners' convenience.

It is submitted the vessel appears worthy to remain as classed, with fresh record of Survey, subject to the indented plates being faired at Owners' convenience.

Wd A. I.
"Span & R."
5.16. Nwc.

Supt.

Ele

26. 5. 16



© 2020

Lloyd's Register
Foundation
W856-0086