

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 7th Dec 1915 When handed in at Local Office 7th Dec 1915 Port of LondonNo. in
Reg. Book.

Survey held at Ipswich

Date, First Survey 23rd OctLast Survey 29th Nov 1915

(No. of Visits)

4

Master

2267 on the Wood, Iron or Steel Yawl "Hetty"

TONNAGE:-

GROSS 107

UNDER DECK 107

NET 90

Built at Kimpin a/d. Ysel

By whom A. J. Otto & Sons

When 1903 - 4

Owners F. L. Harlock

Port belonging to London

Owners' Address

(if not already recorded in Appendix to Register Book)

Surveyed Afloat or in Dry Dock? Afloat Name of Dock Messrs. G. & Co. Ltd. Destined Voyage Coasting

WB=CellDBorDBa

feet; uE&B

feet; f

feet; }

total capacity

tons. FPT

tons; APT

tons; MT

feet

tons. }

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.
* for Special Survey.
Date of last Survey and of
Periodical Surveys.Years
Assigned
now
expired.Machinery and Boiler
Surveys
(including date of N.B., if any).

+100 A.I.

Large 1-13

S.S. Har. N° 2-13.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 76570 Port Lon

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

Society's Freeboard (if assigned) as painted on Ship and now verified } 1 ft. 0 ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? / Was a damage report made by anyone else? If so, by whom? /

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Special Survey N° 3.

The vessel placed on blocks, the bottom and rudder examined, cleaned and recoated.

The hold, peak space, also crew space, cleared, linings removed, ceiling lifted fore and aft, and the steelwork examined throughout, scaled and coated where necessary. The deck, masts, spars, rigging & general equipment examined, pumps, windlass and steering gear examined, hatchways, hatches and fore and afters examined, cables ranged and anchors examined.

It was not considered necessary to drill the shell plating, same found in good condition. Repairs: Several hatches renewed. Minor repairs effected to rigging. Cement in hold renewed in various places. P.T.O.

SUMMARY OF DAMAGE REPAIRS:-

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:-
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE

Decks	Good	Stringers	Good	Dblg. Plates under Sounding Pipes	Good	Copper, or Y.M. of Wood Vessels	✓
Caulking of Decks	"	Inner Bottom Plating	✓	Engine Room Skylights	✓	(State if on Felt.)	
Waterways	"	State if Tanks have been examined inside	✓	Coal Bunkers, Open'gs, Lids, &c.	✓	When put on, Month	Year
Coamings	"	State if Tanks now tested	✓	Scuppers	Good	Boats	Good
Beams & Fastenings	"	Bulkheads	Good	Cargo Hatchways	"	Masts, Yards, &c.	"
Outside Plating	"	Ceiling	"	Hatches	"	Condition, how ascertained	8" aloft
Caulking of ditto	"	Cement or Asphalt (State which.)	"	Planing of Wood Vessels	✓	(State if wedges removed)	✓
Rivets	"	Rudder	"	Caulking	ditto	Sails	Good
Breasthooks & Crutches	"	Steering gear and its connections	"	Treenails	ditto	Equipment letter	6
Transoms	"	Windlass	"	Breasthooks & Stemson	ditto	Anchors, No. of	3 B 15 1 K
Frames	"	Have Pumps now been examined and found efficient?	✓	Transoms, Pointers, & Crutches ditto	"	Cables (State if now ranged)	✓
Reverse Frames	"	Have Sluice Valves now been examined and found efficient?	✓	Timbers of Frame at openings	ditto	" length	120 ft
Floors	"	Have Watertight Doors now been examined and found efficient?	✓	Ditto ditto at other places	ditto	" Rule length	120 ft
Keelsons	"			Stringers, Clamps & Shells	ditto	Hawser & Warps	Good
				Salting (State if examined.)	ditto	Standing & Running Rigging	"

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:- "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

This vessel is now in a good and efficient condition & in my opinion eligible to remain as now classed, and to have fresh record of survey 11-15 & notation of S.S. Ips. N° 3-11-15.

Survey Fee (per Section 22) £ 3 : 0 : 0

Fees applied for,

Special Damage or Repair Fee (if any) £ :

Received by me,

Travelling Expenses (if chargeable) £ 2 : 11 : 6

Second Surveyor's Fee (if any) £ :

Surveyor to Lloyd's Register of Shipping.

Committee's Minute

TUE. 14 DEC. 1915

Character Assigned

Wood

Barge

S.S. Ips. N° 3-11-15

FULL CERTIFICATE
WRITTEN

© 2020

Lloyd's Register
Foundation

W866 - 0005

A. E. Falmer

AT THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

ANCHORS.

If Patent state name of Patentee

Stackless Male Mechanical Tests

CHAIN CABLES.

Iron Stream Chain
or Steel Wire...