

St
II

1

1 JUN 1917

Chief Ship Surveyor

31.5.17

Received from Chief Ship Surveyor

NAME

St. S. Rockwood

Rpt.

Sld.

No.

76995

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.

of Survey

DAMAGE.

Condition

Damage through

Collisions

& Cause

not stated

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed							
Removed and faired or repaired.....							
Faired or repaired in place.....	H						

Other items:-

Bulwarks Repaired & minor Repairs Effected.

Vessel Examined in Dry Dock bottom recoated, hatches renewed as necessary & minor Repairs carried out

It is submitted the vessel is worthy to remain as classed with

record of Survey 5.17 as recommended

100 A. 1

5-17

Sld.



© 2020 Lloyd's Register Foundation

W867-0087