

Received by Chief Ship Surveyor 26-8-15

Received from Chief Ship Surveyor 28 AUG 1915

VESSEL'S NAME S.S. "Iquis" 77 Rpt. huc. No. 64884.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

DAMAGE.

Nature of Survey

Damage through grounding

now repaired as follows:-

	Plates	Frames (Bottom)	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed	1	28		-			
Removed and faired or repaired.....	28	-		-			
Faired or repaired in place.....	13	6		2			

Other items:- Vessel examined in Dry Dock Bottom coated.

Kedge anchor of required weight & test placed on board.

Minor repairs effected.

Shell plating in way of Tank Division between nos. 1 & 2 Tanks found slightly set up but, in Surveyor's opinion, is of too slight a character to require repairing

It is submitted the vessel is worthy to remain as classed with

record of Survey 8-15 as recommended

100 A.1.

8-15 huc.

Wmbs
24-8-15



© 2021

Lloyd's Register
Foundation

W872 0020

aster ink.
on or below