

2017.16.

Sent to Chief Surveyors 1-12-16

Received from Chief Surveyors

Rpt. Gb. No. 3649H.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement,"—*Extract from Sub-Committee's Report 245/92.*)

SURVEY PARTLY HELD

And verification of
reassigned freeboards

When proposed to be completed hot-skates

Portion of Survey held, &c.,

To complete the Survey all the Rule requirements remain to be complied with except examination of Chain Cables & Chain Lockers. The Class of this vessel is Subject to repairs being effected to indented shell plating on Port side forward and to collision damage referred to in Dunedin Rpt. No. 482.

Wm. L. Webb
5-12-'16

© 2021

Lloyd's Register
Foundation

W872-0181