

ed by Chief Ship Surveyor 9-10-'17

Received from Chief Ship Surveyor 9 OCT 1917

SEL'S NAME Steel S. S. "Gerasimos"

Rpt. Msl.

No. 4655

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

e of Survey Collision damage

The class of this vessel is subject to some shell plating, repaired by the oxy acetylene process, being specially examined at next dry docking.

The marseilles Surveyors now report that some slight indentations on starbo. side of bridge plating, have been examined & may, in their opinion, be repaired at Owners' convenience.

Nothing has yet been done towards the 15th Special Survey No. 1, due 6.17.

It is submitted action be deferred.



© 2020

Lloyd's Register
Foundation

W574-0059