

Is the screw shaft fitted with a continuous liner the whole length of the stern tube yes Is the after end of the
in the propeller boss yes If the liner is in more than one length are the joints burned yes If the liner does not

Copy.

14th April, 1916.

Copy of Message passed on April 14th 1916 between The Glen Line
(McGregor, Cow & Co.) Ltd London and Messrs. R. & W. Hawthorn,
Leslie & Co. Ltd, Hebburn Shipbuilding Yard, Hebburn, on, Tyne.

.....

RECEIVED:- 5-35 p.m.

SENT

s.s. "Glenogle" - damaged bedplate!

We will agree to accept
repaired casting provided same
is carried out in accordance
Lord Pirrie's suggestion.
Posting sketch and writing fully
to-night.

N



© 2020

Lloyd's Register
Foundation

Thickness 1" Material of Lower back plate Steel Thickness 1" Greatest pitch of stays 14 1/2" Working pressure
Thickness 1" Material of tube plates 1" Thickness Front 1" Back 3/4" M