

st of

Greenock.

Continuation of Report No. 17425 dated

Continuation of Report No. 17425 dated 17th March, '19, on the

Stem "Sawyer" "Helcia".

Plating A 10 ft. Starboard side. Caulked ~~stern~~ ^{stern} ~~port~~ ^{port} removed, and
Plating at foot of stem frame. Both sides, caulked.

To complete the survey (S.S. 1903), vessel requires to be thoroughly examined internally, pumps & watertight door examined, cables & rigging, and repairs to keel & shell plates effected. The owners state this will be done at Guinnity within about three months time. Truly yours, Wm. J. S. S. S.

A. Hartman

17-3-19

Following form:—

[illegible]

When and where
Superinten