

REPORT of SURVEY for REPAIRS

Date of Writing Report *10 Mar 1902* When handed in at Local Office *Cardiff* Port of *Cardiff* and Last Survey *3rd March 1903*

No. in Reg. Book *30 Sept on the Wood, Iron or Steel* Date, First Survey *Sc. Sh. Kelvinside* (No. of Visits) *1* Master *E. A. O'Neal 9th-02*

Survey held at *Sunderland* By whom *Short Bros. Ltd.* When *Glasgow*

TONNAGE: GROSS *3250* Owners *Glasgow Steam Shipping Co. Ltd.* Port belonging to *As recorded.*

NET *As recorded.* Owners' Address *As recorded.* Destined Voyage *As recorded.*

Surveyed *As recorded.* in Dry Dock? *Yes* Name of Dock *But.* Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

WB=CellDBorDBa feet; uE&B feet; APT feet; MT feet; tons. *100 AI (Steel) Spar deck 2.02*

total capacity tons. FPT tons; APT tons; MT feet; tons. *2.02*

N.B.—All alterations in the existing records should be underlined. If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. *2684* Port *Cardiff* *Docking:—*

REPAIRS, OR EXAMINATION AS PER RULE, FOR *Docking:—*

Vessel now placed in dry dock, bottom & rudder cleaned, examined and coated and found satisfactory

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Paired or Repaired								
Paired or Repaired in place								
PRESENT CONDITION OF THE	<i>Good</i>							
Decks		Stringers	<i>Good</i>		Dblg. Plates under Sounding Pipes	<i>Good</i>		Copper or Y.M. of Wood Vessels
Caulking of Decks		Inner Bottom Plating			Engine Room Skylights			(State if on hull.)
Waterways		State if Tanks have been examined inside			Coal Bunkers, Open'gs, Lids, &c.			When put on, Month
Coamings		State if Tanks now tested	<i>Good</i>		Scuppers			Year
Beams & Fastenings		Bulkheads			Cargo Hatchways			Boats
Outside Plating		Ceiling			Hatches			Masts, Yards, &c.
Caulking of ditto		Cement or Asphalt (State which.)	<i>Good</i>		Planking of Wood Vessels			Condition, how ascertained
Rivets		Rudder			Caulking ditto			(State if wedges removed)
Breasthooks & Crutches		Windlass			Treenails ditto			Sails
Transoms		Have Pumps now been examined and found efficient?			Breasthooks & Stemson ditto			Equipment letter
Frames		Have Sluice Valves now been examined and found efficient?			Transoms, Pointers, & Crutches ditto			Anchors, No. of
Reverse Frames		Have Watertight Doors now been examined and found efficient?			Timbers of Frame at openings ditto			Cables (State if now ranged)
Floors					Ditto ditto at other places ditto			length (on board)
Keelsons					Stringers, Clamps & Shells ditto			Rule length (per Table 22)
					Salting (State if examined.)			Hawsers & Warps
								Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c."

This vessel appears to be in good condition and the report on same is forwarded for the information of the Committee

Office Fee (if chargeable) per Scale II, Sec. 22 £
Survey Fee (per Section 28) £
Special Damage or Repair Fee (if any) (per Sec. 28.) £
Travelling Expenses (if chargeable) £
Second Surveyor's Fee (if any) £

Fees applied for, £19
Received by me, £19

M. Macleod

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute
Character Assigned

FRI. MAR 14 1902



© 2020
Lloyd's Register
Foundation