

Report of Survey for Repairs, &c., of Engines and Boilers.

COPY.

Lloyd's Register of Shipping.



Port Colombo,

16th October, 1940.

This is to Certify that

I, H. NIGHTINGALE,
the undersigned Surveyor to this Society did at the request of
Messrs. Shaw Wallace & Co., Ship's Agents, attend on board the
M.V. "TEDDY", No. 84566 in the Register, on October 3rd 1940 and
subsequent dates for the purpose of carrying out the Annual Donkey
Boiler Survey.

Both Donkey Boilers were examined internally and externally, also all valves, cocks, mountings, bearers and chocks and all were found to be in good condition.

The safety valves were set to the allowable pressure of 150 lbs. per square inch, the thickness of the washers being

PORT BOILER

STARBOARD BOLLER

Port

Starboard

Port

Starboard

8.2 mm

9.0 mm

8.9 mm

8.1 mm

Survey Fee (3 visits)	Rs.180/-
Travelling Expenses	" 9/-
	<u>Rs. 189/-</u>

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

“While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society.”

(Rpt. 10) 20m, 2.40. (MADE AND PRINTED IN ENGLAND)

W89-0204