

Report of Survey for Repairs &c. of Engines and Boilers.

COPY.

Lloyd's Register of Shipping.

Port Colombo,

18th October, 1940.



This is to Certify that

I, H. NIGHTINGALE,
the undersigned Surveyor to this Society did at the request of
Messrs. Shaw Wallace & Co., Ship's Agents and Messrs. Aitken Spence
& Co. Ltd., Lloyd's Agents, attend at the Colombo Port Commission's
Testing Sheds on October 9th 1940 for the purpose of witnessing a
test on one length of Anchor Cable from the M.V. "TADY", No. 24566
in the Register.

When Anchors or Cables are tested

Number of Certificate.	Anchors.*	WEIGHT		Remarks
		Ex. Stock	Qrs.	
1st Bower ...				
2nd "				
3rd "				
Collective Weight.				
Stream				
Kedge.....				

* When a bower anchor is tested

Number of Certificate.	Length and size supplied.		Remarks
	Length.	Diam.	
	Fathoms.	Ins.	
Iron Stream Chain or Steel Wire...			

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

COPY.

Lloyd's Register of Shipping.

Port Colombo,

18th October, 1940.



This is to Certify that

I, H. NIGHTINGALE,
the undersigned Surveyor to this Society did at the request of
Messrs. Shaw Wallace & Co., Ship's Agents and Messrs. Aitken Spence
& Co. Ltd., Lloyd's Agents, attend at the Colombo Port Commission's
Testing Sheds on October 9th 1940 for the purpose of witnessing a
test on one length of Anchor Cable from the M.V. "TADY", No. 24566
in the Register.

A new end link had been fitted and the prescribed test of 101½ tons
was applied. The new end link withstood the test but a stud
link was found to be cracked. A new stud link was fitted but
on subjecting the cable to test on October 11th 1940, this link
broke at 69 tons load. As any further repair would delay the
vessel, recommended that the broken cable be put aboard and
repaired at first convenient opportunity.

Survey Fee (2 visits) Rs. 40/-
Travelling Expenses " 4/-
Rs. 44/-

H. Nightingale
Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

W89-0205