

## REPORT of SURVEY for REPAIRS, &amp;c.

Date of writing Report 19 When handed in at Local Office 19 Port of London  
No. in Survey held at London Date, First Survey 1915 Last Survey 18 Jan 1915  
Reg. Book. on the Wood, Iron or Steel &c. *Figulina* (No. of Visits) Master

## TONNAGE:-

GROSS 1034.

UNDER DEK. 841.

NET 560.

Built at Sunderland

By whom Colburn Graham &amp; Co. When 1913

Owners Cie. Em. d'Anthracite (A. Anthracite, Ltd.) Port belonging to Rouen.

Owners' Address

(if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? Dry Dock Name of Dock *Thurston Dock* Destined VoyageWB=Cell DBor DBa feet; uE&B feet; f feet; }  
total capacity tons. FPT tons; APT tons; MT tons. }

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 1828 Port *London*

Particulars of Classification (which must be inserted precisely as in Register Book &amp; Supplements).

CHARACTER.	Year and Month	Machinery and Boiler
For Special Survey. Date of last Survey and of Periodical Surveys.	Year and Month	Surveys (including date of N.B., if any).
<i>100. 7. 1.</i>	<i>11-13.</i>	<i>L.M.C.</i>
		<i>11-13.</i>

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes, and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined?

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR *Docking Survey with view to change of Ownership. Particulars of same not obtained.*

*The vessel now placed in dry dock, the bottom examined cleaned and painted.*

*On port side found the 5th plate from stem slightly indented on each side of one frame, the riveting and caulking made good otherwise the indent have not been dealt with, and in my opinion no further action is necessary with regard to same. The middle part of the stern frame is slightly bowed forward between keel and 1st quadrant above, this being in my opinion merely a blemish, and as same does not affect the efficiency of the stern frame, action in regard thereto is not deemed necessary.*

## SUMMARY OF DAMAGE REPAIRS:-

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:-
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

  

PRESENT CONDITION OF THE	Stringers	<i>good</i>	Dbing. Plates under Sounding Pipes	<i>good</i>	Copper or Y.M. of Wood Vessels	
Decks	Inner Bottom Plating	<i>no.</i>	Engine Room Skylights	<i>good</i>	(State if on Vell.)	
Caulking of Decks	State if Tanks have been examined inside	<i>no.</i>	Coal Bunkers, Open'gs, Lids, &c.	<i>good</i>	When put on, Month	Year
Waterways	State if Tanks now tested	<i>no.</i>	Seuppers	<i>no.</i>	Boats	<i>good</i>
Coamings	Bulkheads	<i>good</i>	Cargo Hatchways	<i>no.</i>	Masts, &c.	<i>no.</i>
Beams & Fastenings	Ceiling	<i>good</i>	Hatches	<i>no.</i>	Condition, how ascertained	<i>from deck</i>
Outside Plating	Cement or Asphalt (State which.)	<i>good</i>	Planking of Wood Vessels	<i>no.</i>	(State if wedges removed)	<i>no.</i>
Caulking of ditto	Rudder	<i>good</i>	Caulking	ditto	Sails	<i>not seen</i>
Rivets	Steering gear and its connections	<i>no.</i>	Treenails	ditto	Equipment letter	<i>m.</i>
Breasthooks & Crutches	Windlass	<i>no.</i>	Breasthooks & Stemson	ditto	Anchors, No. of	<i>3 B. 15. 1 K.</i>
Transoms	Have Pumps now been examined and found efficient?	<i>no.</i>	Transoms, Pointers, & Crutches	ditto	Cables (State if now ranged)	<i>no.</i>
Frames	Have Sluice Valves now been examined and found efficient?	<i>no.</i>	Timbers of Frame at openings	ditto	" length (on board)	<i>size</i>
Reverse Frames	Have Watertight Doors now been examined and found efficient?	<i>no.</i>	Ditto ditto at other places	ditto	" Rule length	<i>size</i>
Floors		<i>no.</i>	Stringers, Clamps & Shells	ditto	Hawser & Warps	<i>good</i>
Keelsons		<i>no.</i>	Salting (State if examined.)	ditto	Standing & Running Rigging	<i>no.</i>

## General Observations, Opinion as to Class, Recommendation, &amp;c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,11," or "to remain as classed and to have record of survey, 1,11, and the notations of ss No. 1-11 and ptd 11, &c."

*This vessel is now in good condition, and eligible in my opinion to remain as classed with fresh record of survey 1-15 and the necessary changes for new Owners etc. to be made in the Register Book.*

Survey Fee (per Section 25)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 25)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

Surveyor to Lloyd's Register of British &amp; Foreign Shipping.

Committee's Minute

Character Assigned

FRI. JAN 29. 1915

*10001*  
*W. subject.*

© 2020

Lloyd's Register Foundation

W891-0129