

sp "Enosis."

Qns. Rpt. 3323.

It is submitted that this report should be returned to the Queenstown Surveyor for his recommendations which are omitted from the report.

He should be requested to state whether he examined the machinery repairs that were stated to have been been effected at the River Plate.

© 2020

Lloyd's Register  
Foundation

W892-0129

JLM

JWZ

29/10/15

29/X/15