

22 NOV 1916

1

Surveyor 21-11-16

Received from Chief Ship Surveyor

Steel S.S. "French Rose"

Rpt. Hul.

No. 29653.

The Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

ment to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also at clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Condition and DAMAGE.

through collision & raving against a Pier Head.

red as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
.....	-						
nd faired)	1						
ired.....)							
repaired)	3						
.....)							

as:-

Vessel examined in Dry Dock. Bottom cleaned & coated. Bulwark Plating, Rail & Stanchions repaired as necessary. Minor repairs effected.

A Bower anchor has been taken ashore to be repaired, it is stated this anchor will be forwarded to London & placed on board there.

tted the vessel is worthy to remain as classed with of Survey 11-'16 as recommended Subject as above.

100 A.1. }
11-'16 Hul. } subject etc.

London
22-11-16

© 2020

The London Surveyors signed the above



Lloyd's Register Foundation

W 303 2046