



Received from Chief Ship Surveyor 21 AUG 1917

by of Ship Surveyor 20.8.17
EL'S MA Steel & S. "Harewood" Rpt. Mlt. No. 914.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The object of this report is to give a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to point out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points in the endowment."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey Damage { 1ST S.S. no. 1, due 4.17 & partly held as per h. Y. Rpt. 13046

This vessel is reported by the Malta Surveyor to have sustained damage to Counter & Poop side plating, frames, beams, etc. through collision.

The vessel has proceeded to her loading port where the Surveyor recommends that either temporary or permanent repairs should be effected.

It is submitted action be deferred, the Owners informed of the Surveyor's recommendation and asked to state where & when the required repairs will be effected.

111
© 2020
21-8-17
W900-0034
Lloyd's Register Foundation