

2m.7.16.

Wrecked 15

WRECK BOX

15. Bottom.

Received by Chief Ship Surveyor

11. 9. 16

Received from Chief Ship Surveyor

VESSEL'S NAME

St. S. S. Hinton

Rpt.

Npt

No.

18710

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Condition

Damage (cause not stated)

GOVERNMENT SERVICE.

This vessel has been placed in dry dock, the bottom cleaned and coated.

On starboard side No.3 plate in "B" strake found set up between two frames; the cement in way of same has been made good and the frame rivets re-caulked. No.6 plate in "F" strake & landing of plate next about found set in; the riveting & caulking in way has been overhauled and made good.

It is stated the repairs will be dealt with at first convenient opportunity.

Vessel on Admiralty Charter.

It is submitted the vessel appears worthy to remain as classed, with fresh record of survey, subject to the indented shell plates being dealt with at a convenient opportunity.

100 A. I.

9. 16 Rpt.

[Signature]

12. 9. 16

Savys

Etc

W907-0056



© 2020

Lloyd's Register Foundation