

total

of the
girder

La

4 MAY 1917

by Chief Ship Surveyor 3. 5. 17

Received from Chief Ship Surveyor

EL'S NAME Stl. S.S. "EAGLE".

Rpt. Lon. No. 79875

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Condition

re of Survey

This vessel has been placed in dry dock, the bottom cleaned and coated and minor repairs effected.


The bow plates—port & starboard sides—in "C", "D" & "E" strakes and the stem plates in "B" strake found indented; and the Surveyors recommend same be dealt with at the next Special Survey.

It is submitted the vessel appears worthy to remain as classed, with fresh record of survey, subject to the indented shell plates being dealt with at the next Special Survey; and the Owners should be informed accordingly.

100 A. 1.

4-16 Lon.

3. 5. 17



© 2020

Lloyd's Register
Foundation
W909-0082