

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 5.9.18 When handed in at Local Office 5.9.18 Port of Philadelphia Pa
No. in Survey held at Philadelphia Pa Date, First Survey 13.8.18 Last Survey 4.9.19
Reg. Book. 97 on the Wood, Iron or Steel Se. St. Cupion (No. of Visits 14) Master A.C. Calver
TONNAGE:— Built at Alloa N.B. By whom Mackay Bros When 1914-2
GROSS 3575 Owners Cupion S. S. Co. Ltd. Port belonging to London
UNDER DK. 3095 Owners' Address London
NET 2201 (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? and Name of Dock Cramps Destined Voyage U.K.

WB=CellDBorDBa feet: uE&B feet: f feet: f
total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 1606 Port N. C. S.

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

CHARACTER, for Special Survey, Date of last Survey and of Periodical Surveys.	Years Assigned Annual Survey.	Machinery and Boiler Surveys (including date of N.B., if any).
<u>+100 A-1</u> <u>9.17</u>		<u>+LMC 2.17</u> <u>T.S. 1.17</u>
<u>Corny Petroleum</u> <u>in Bulk</u>		<u>5 ft 2 ins.</u>

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? none Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Special Survey "1"
Vessel placed in Drydock, Bottom & Rudder cleaned, examined & coated, all cargo & fuel oil tanks, fore & aft Peaks, Double Bottom Tanks & Cofferdams cleaned, examined & tested to rule, all good. Pump room, forehold, Engine & Boiler spaces & all Bunkers space examined, all good.
Decks, all deck erections, Hatchways, Coamings, Hatch covers, Boats, Anchors, Cargo Pumps, Mast, Spars & Rigging, Windlass, Steering gear & connections all examined, all now good.
Freeboard verified.

SUMMARY OF DAMAGE REPAIRS:—

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE

Decks	<u>Good.</u>	Stringers	<u>Good</u>	Dblg. Plates under Sounding Pipes	<u>✓</u>	Copper, or Y.M. of Wood Vessels	
Caulking of Decks	"	Inner Bottom Plating	"	Engine Room Skylights	<u>And</u>	(State if on Felt.)	
Waterways	"	State if Tanks have been examined inside	<u>yes</u>	Coal Bunkers, Open'gs, Lids, &c.	"	When put on, Month	<u>Year</u>
Coamings	"	State if Tanks now tested	<u>yes</u>	Scuppers	"	Boats	<u>Good.</u>
Beams & Fastenings	"	Bulkheads	<u>Good.</u>	Cargo Hatchways	"	Masts, Yards, &c.	"
Outside Plating	"	Ceiling	"	Hatches	"	Condition, how ascertained	<u>from Deck</u>
Caulking of ditto	"	Cement or Asphalt	<u>Both good</u>	Planking of Wood Vessels	"	(State if wedges removed)	"
Rivets	"	(State which.)	<u>Good.</u>	Caulking ditto	"	Sails	"
Breasthooks & Crutches	"	Rudder	"	Treenails ditto	"	Equipment letter	<u>U</u>
Transoms	"	Steering gear and its connections	"	Breasthooks & Stemson ditto	"	Anchors, No. of	<u>3. B. 1. S. 1. K.</u>
Frames	"	Windlass	"	Transoms, Pointers, & Crutches ditto	"	Cables (State if now ranged)	"
Reverse Frames	"	Have Pumps now been examined and found efficient?	<u>yes</u>	Timbers of Frame at openings ditto	"	" length (on board) size	"
Floors	"	Have Sluice Valves now been examined and found efficient?	<u>yes</u>	Ditto ditto at other places ditto	"	" Rule length size	"
Keelsons	"	Have Watertight Doors now been examined and found efficient?	<u>✓</u>	Stringers, Clamps & Shells ditto	"	Hawser & Warps	<u>Good</u>
				Salting (State if examined.) ditto	"	Standing & Running Rigging	"

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptdN15, &c."

This vessel is now in a good & efficient condition, eligible in my opinion to remain as classed +100 A-1 & to have fresh record of Survey 8-18 & notation of Special Survey now completed S.S. Phila. No. 1-18

Survey Fee (per Section 28) £80.00

Special Damage or Repair Fee (if any) £

Travelling Expenses (if chargeable) £2.00

Second Surveyor's Fee (if any) £

Fees applied for,

9/4 19 1800

Received by me,

19

W. Watters.

C. F. Macdonald.

Surveyor to Lloyd's Register of Shipping.

Committee's Minute

New York SEP 10 1918


Character Assigned

100 A-1 Carr. Ret. in bulk.

Subd for oil fuel 2.14 2.14 15007.

S.S. No. 1-18 + LMC Mtd 8.18 B.S. 3.18

T.S. 8.18



Lloyd's Register
Foundation

W912-0109

Repairs now done.

Several defective rivets in way of Starboard Hawse pipes at bottom renewed.

Two shell lugs in Fore Peak 2nd Stringer Std. side defective rivets renewed. Several defective rivets in way of No. 1 Tank, boundary angle, Std. side Ford. renewed.

Six defective rivets aft. Peak Tank shell plating now renewed. Six zinc plates in Stern frame missing now renewed. About 12 defective rivets in shell plating through out the Vessel now renewed.

Windlass opened up for examination, all good.

Steering fear & connections opened up for examination all now good.

After plates examined & defective rivets in way of
Transom frames renewed, all now good, See special
Reasons List

W. R. Waters

C. J. McDonald

When Anchors or Cables are supplied, the particulars are to be reported in the following form:—

ANCHORS.

[illegible]

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd power.

CHAIN CABLES.

[illegible]