

12-18

Received by Chief Ship Surveyor 6.3.18

Received from Chief Ship Surveyor

7 MAR 1918

VESSEL'S NAME

Ste % Denise

Rpt.

Cy

No. 40353

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

1st S.S. No. 1 AND DAMAGE.

Damage through striking a submerged object & collision & grounding.
(See SWS rpts 14150 & 14444)
now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed							
Removed and faired or repaired.....	14	22		15			
Faired or repaired in place.....	9	13		14			

Other items:- Bridge front bulkhead repaired & minor repairs effected.
Bottom cleaned, examined & coated.

The 1st S.S. No. 1 has also been ^{completed & minor} held and following repairs done due to wear and tear: With the following exception:-

The Downton pump was found to have been removed for gunners accom^{ts}. Arrangements will be made to have this refitted when vessel returns to France & submitted for inspection at the first opportunity.

It is submitted the vessel is worthy to remain classed with record of Survey 2.18 and notation of SS. SWS No 1.17. Subject to the Downton pump being refitted & examined as recommended.

10021

2.18 Cy

SS SWS No 1.17

Subject. etc.



© 2020

Lloyd's Register Foundation