

Surveyors 24. 9. 18

Received from Chief Surveyors 26 SEP 1918

NAME Ats. Carmen

Report Gen. No. 5423

**For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/12.)

Survey Equipment. When due

all letter  
rec 21/9/17

Some shell plating indented through stranding requires to be repaired, a bower anchor and 105 fathoms of chain require to be supplied.

The Copenhagen Surveyors now state they are informed the vessel is detained at Cuxhafen and the Owners are making arrangements to have the vessel's equipment completed there.

It is submitted action be deferred.



© 2020

Lloyd's Register

24. 9. 18.

Foundation