


cf "Carmen".

Cpm Rpt 4773.

It is submitted that the Copenhagen Surveyors should be requested to state whether they are correct in stating that the diameter of the H.P. cylinder is 14" in their report whereas in the launching report they stated it was 15."

They should be asked to state whether the superheater safety valve is fitted with means of lifting & turning the valve, in order to test its efficiency under steam, in accordance with Section 3 par 6. & 8. of the Rules. They should also state whether the same applies to the ^{cf} Anna ^{Cpm Rpt.} 4757.

20.10.14



Lloyd's Register
Foundation