

of the tank, and of the inner bottom plating, especially in the boiler space.
Last Report. No. 74599 Port Liv

7-100 A1

1

Wreck 10

WRECK BOX
No. 10. Bottom.

Sent to Chief Surveyors 10-6-'16

Received from Chief Surveyors

VESSEL'S NAME Steel S.S. "Counsellor" Report Liv. No. 44942.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey Completion of 1st S.S. no. 3 When due 5-'15

Notes

RECEIVED
177
13-6-'16
8



© 2020
Lloyd's Register
Foundation

W941-0230

Received by me,