

total
of the
girder

Wreck 11

Wrecked 9 12

3

WRECK BOX
No. 12 11 Bottom

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

S.S. "Dacre Castle"

Rpt.

Yka

No.

1096

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey

Compt^m 1st S.S. No. 1 AND DAMAGE.

Damage through

Grounding

now repaired as follows:-

(see Yka. rpt. 1616)

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed	1						
Removed and faired or repaired.....	10						
Faired or repaired in place.....	3	12		12			

Other items:-

Vessel examined in Dry Dock Yudder
Pintles renewed & minor repairs. Port lower bunker
recoated.

The 1st

S.S. No. 1

has also been ~~held~~ ^{Completed} and following repairs done

due to wear and tear:-

bottom recoated & minor repairs

RETAIN

It is submitted the vessel is worthy to remain classed

with record of Survey

8. 12 Yka

and notation of

S.S. Yka No 1. 12

Yka. rpt. 1549
as recommended.

100 A.1

Shelter dk with freeboard
8. 12 Yka.

S.S. Yka No 1. 12.

W.D. 6.9.12
Lloyd's Register
Foundation

2500-6561