

Engine Room
Gross Tonnage
Less Crew Space
Less above Crew
Less below Crew

Chief Ship Surveyor H. D. R.

Received from Chief Ship Surveyor

NAME Sh. S.S. Dalegarth Force Rpt. Dun. No. 7801

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

First Entry

The Hull Surveyors should be informed that this vessel has proceeded to their port for the fitting of her Machinery, and to complete the survey on the hull the following remains to be done:— casing top to be riveted, & engine skylight fitted.

The Surveyors should be requested to give the case the necessary attention, and on completion of the work to forward a report on Form 8 in the usual manner with a view to the classification of the vessel.

At the same time the Dundee Surveyors should be informed it is concluded the side keelson plate in the boiler space is .42 as approved, but the Surveyors should be requested to state if this is so.

15. 12. 13

Los. 15/12/13



© 2020

Lloyd's Register
Foundation

W480-0094