

The vessel was placed in **This is to Certify** that I have

110.17.

to Chief Surveyors 5-2-'18

Received from Chief Surveyors _____

SEL'S NAME Steel S.S. "Abrins" Report Pos. No. 971.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

re of Survey Condition When due _____

Notes:

The Class of this vessel is subject to some indented plating and one plate of no. 6 tank top being permanently repaired at Owners' convenience.

M. Lomb
5-2-'18
© 2020
w969-002

- I. of Wood Vessels.....
- in Felt.).....
- in, Month.....
- &c.....
- ascertained.....
- edges removed).....
- ter.....
- f 38/51.....
- if now ranged).....
- oard).....
- yth.....
- rps.....
- aning Rigging.....

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society.

Lloyd's Register
Foundation

to remain as