

Owners John Mount S. S.  
Managers Hope & Sloan  
(Where necessary to be entered in Reg. Book.)

(1m,1,4.)

1.

Sent to Chief Surveyors 7.4.04

*Received from Chief Surveyors*

VESSEL'S NAME St. S. Ashmont Report Eng. No. 13874

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

### Nature of Survey

First entry

*When due*

† 100 Al ("Steel")

1 DR (Sta) & deep framing.

N.B = Call DB at 124' f138' 751E APT 956

FK 68H Cem. Lloyd AACP P25 B118' F30'

u. *Claydi AYCP* P25 B110

C. H. J.  
7/4/04

W970-0156

© 2020

	ness	30	6
		$3 \times 3 \times$	6
	(Shut)		6
	ath & thickness	42	8
		$3\frac{1}{2} \times 3\frac{1}{2} \times$	8
	and thickness (Shut)		6

**PILLARS, In 'tween Deck, size and spacing**

" Hold (Increased at ends.)  
 " ~~Quarter 'tween Dks,~~ " "  
 " "

公

48

42

48

”

Tie Plates

Deck, Material and thickness *✓ 5/8*

8

.....