

3m.4.18.

WRECK BOX  
14

23.

Received by Chief Ship Surveyor

28.9.18

Received from Chief Ship Surveyor

-2 OCT 1918

VESSEL'S NAME Steel S/S "AQUARIUS".

Rpt. Gib.

No. 115

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Damage. (1<sup>st</sup> SS No 3 due 5-16 pr Leas. Ex<sup>5</sup> 6.18)

The 1st. s.s. No. 3 became due 5/16 and has been partly held by the examination of the bottom in dry dock. The tank top under boilers requires to be dealt with at the special survey. An indented plate on starboard side requires to be dealt with at the Owner's convenience.

"Examined 6/18" has been recorded.

The Gibraltar Surveyor now reports the vessel to have sustained damage to boat davits and bulwark plating etc. through collision. Partial and temporary repairs have been effected and the Surveyor recommends permanent repairs within a reasonable time.

It is submitted action be deferred.



© 2021

Lloyd's Register  
Foundation

30. 9. 18.

1000-876m