

Copy
(Received at London Office)

REPORT of SURVEY for REPAIRS, &c.

No. 72636

Writing Report... 19... When handed in at Local Office... 30.12... 19... Port of Newcastle-on-Tyne
Survey held at North Shields
Date, First Survey 22nd Dec. Last Survey 23rd Dec. 1919
No. of Visits

TONNAGE:-
2240
1844
1330
Built at Tyneside
Owners Shipping Controller
Owners' Address
By whom T. & S. Iron Works
Master
When 1919
Port belonging to
(if not already recorded in Appendix to Register Book)

veyed Afloat or in Dry Dock?
Name of Dock
Destined Voyage
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Medical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; besides being detailed in the body of the report, the particulars should be clearly stated in the space provided on back of this form. State also the dates and initials of any letters respecting this case.

Was a damage report made by anyone else? If so, by whom?

How done:-
Vessel placed on Pontoon, bottom & Rudder cleaned examined and recoated. At the request of the owner the shell plating was drilled to ascertain the thickness. At the time was limited only under water particulars were taken.

A" stake inside	59" x 1/20"	"	"	"	"	"	"	"	"
B" " outside	59" x 1/20"	"	"	"	"	"	"	"	"
C" " inside	59" x 1/20"	"	"	"	"	"	"	"	"
D" " outside	59" x 1/20"	"	"	"	"	"	"	"	"
E" " outside	69" x 1/20"	"	"	"	"	"	"	"	"
F" " inside	58" x 10/20"	"	"	"	"	"	"	"	"

Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:-

Stringers	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels.
Inner Bottom Plating	Engine Room Skylights	(State if on Felt.)
State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month Year
State if Tanks now tested	Scuppers	Boats
Bulkheads	Cargo Hatchways	Masts, Yards, &c.
Ceiling	Hatches	Condition, how ascertained
Cement or Asphalt (State which.)	Planking of Wood Vessels	(State if wedges removed)
Rudder	Caulking	Sails
Steering gear and its connections	Treenails	Equipment letter
Windlass	Breasthooks & Sterns	anchors, No. of
Have Pumps now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)
Have Sluice Valves now been examined and found efficient?	Timbers of Frame at openings ditto	" length size
Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places ditto	" Rule length size
	Stringers, Clamps & Shells	Hawser & Warps
	Salting	Standing & Running Rigging
	(State if examined.)	

al Observations, Opinion as to Class, Recommendation, &c.:-
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon survey, thus, for example:- "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and pnd15, &c."

above is forwarded for the information of the Committee.

Section 28)
or Repair Fee (if any)
Fees applied for,
Received by me,
Surveyor to Lloyd's Register of Shipping.

FRI MAY 14 1920
FRI MAY 27 1920
TUE OCT. 26 1920
FRI MAY 28 1920
FRI JUN. 18 1920
FRI DEC. 23 1920
TUE SEP. 24 1923
Lloyd's Register Foundation
W988-0276

