

1

FRESNO STAR

Received from Chief Surveyors

Sent to Chief Surveyors

VESSEL'S NAME STEEL S.S. "WOODARRA" Report Gls. No. 39397

For the CHIEF SHIP SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey

When due

The Eye Plates of emergency steering wire hackets require to be nicked.
The Downton Pump has been dispensed with for the present, but it is concluded the Owners are agreeable to fit same when requested.

100 A.1. (steel) "Shelter deck with Freeboard"

2 Dks (steel) & Shelter Dk (steel)

Cell DB 386' 1275 t.


FPT 125. APT 80 t.

FK. 8BH to Shelter Dk.

cem. Lloyds A+C.P.

P 31', F 43' on Shelter Dk.

Mars
11-12-19



© 2020

W989-0155

Lloyd's Register Foundation