



Damage due to striking  
dock wall. 2 Blades of  
the propeller bent.

N.B.—If this Report is copied by copying Press, especial care must be taken that the copying paper is not so much damaged as to spread the ink, or to cause it to show through to the other side.

Screw shaft & propeller to  
be examined in dry dock  
at Barry; now under  
Survey there.

Submitted action be  
deferred pending  
the receipt of a  
reply from Dry.

J.W.D.  
30/1/28

