

S. Herbert A. Pratt

EYK 20356

It is concluded that a spare lubricating oil pump has been supplied as required by the rules, but the surveyor should be requested to state if this is so

H.
22/6/21



© 2020

Lloyd's Register
W992-0255
Foundation

Committee's Minute New York MAY 31 1921

ed. As now, / /