

and this furnace was recommended to be renewed.

Boiler mountings were not opened up for survey. Main steam pipe was removed as recommended for annealing and testing but request to be present at test was not complied with.

L.H.

N.B.—If this Report is copied by copying press especial care must be taken that the copyist places it quite so much dampened as to spread the ink, or to cause it to show through to the other side.

LET THE SURVEYORS BE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



Lloyd's Register
Foundation