

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?


To what pressure were they afterwards adjusted?

*Low* Report No. *16530*

It is submitted that this Report be forwarded to the *Glasgow* Surveyors for their guidance ~~and for completion.~~

*D.S. J.W.*

Date



© 2020

Lloyd's Register Foundation

*... tested by hydraulic pressure & 500 lbs*