

or Repaired in place

CONDITION OF THE

Stringers

Inner Bottom Plating

Dble. Plates under Sounding Pipes

Engine Room Skylights

Copper, or Y.M. of Wood  
(State if on Felt.)  
When put on, Month

Old Report No. 23823.  
New " " 124424

Submitted that these Reports be forwarded to the  
Tide Surveyors for their guidance.

J.R.R.  
16.9.08

16.9.08

© 2020



Lloyd's Register  
Foundation

in my opinion for the class contemplated.