

Yes

To what pressure were they afterwards adjusted under steam? 220 lbs

adjusted under steam?

1m.10.43.

ent to Chief Surveyors.....

Received from Chief Surveyors.....

11 JAN 1945

ESSEL'S NAME "AMERICAN ARROW" REPORT L.As. No. 3184

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

No. 1 SURVEY PARTLY HELD. BS & GE

en due 6.1.44 When proposed to be completed ----

tion of Survey held, &c. Examination of main crankshaft journals, HP crankpin, condensers, inboard main feed pump, starboard bilge and general service pump and megger test of electrical equipment.

Subject to donkey boiler not being used again.

Noted.

Handwritten signature and date 11.1.45



© 2020

Lloyd's Register Foundation

W997-0189

CS 3,34,

is in good and safe working condition

of 12 months, and to have fresh record of B.S. 10-44 in the