

106.

Weyford October 30<sup>th</sup> 1846✓  
Dear Sir

I beg leave to say that the "Dolphin" was shilly in conformity with the rules, Section 35, the only reason the Owner, would not pay for Cladding her bottom hulls is that, she was so new she did not require to be Cladded until the present time, She has been Lacking for Cargo. This vessels beams are all composed of English oak, all brought from Chepstow, the word Oak, before Oak.

WEX 031-0042



Meaning American oak, I regret the omission  
of the Beams, in my report, & will be more  
particular for the future,

your Obedient  
Servant

W Deane

Leicester



© 2021

Lloyd's Register  
Foundation



very good sufficient in size and good in quality

Boat

d

ma

h

repar

Comit

su

car

et

ld


dr

let

1846  
Wexford — 306  
M. Devore

Rec  
Ans

Dolph



Charles Graham Esq.  
Convent Corn Hill  
2 White Lion  
Stoy as Register office  
London



© 2021

Lloyd's Register  
Foundation