Double Bottoms at Solid Floors...	3½	3½	40	3½	3½	40							
„ at intermdt. Bkts.	9	3½	42	9	3½	42							
„		21			26								

KEELSONS & STRINGERS.

Inches in Ship. | Inches in Ship. | Inches in Ship. | Inches per Rule

urveyors *Received from Chief Surveyors*

AME STEEL S.S. "TREMATON" Report Gls. No. 39263

For the CHIEF SHIP SURVEYOR

ases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report*, 24/5/02.)

vey *When due*

The Downton Pump has been dispensed with for the present but it is ided the Owners are agreeable to fit same when requested.

Vessel stated to have sustained damage at the after end of N°2 Hatch, ide, in way of bilge, through striking quay wall. Vessel examined afloat several rivets found sheared and others leaking. Efficient temporary repairs been carried out, but it is recommended that vessel be placed in Dry Dock permanent repairs effected at the first convenient opportunity.

✠ 100 A.1. (steel) } Subject to permanent repairs being effected
1 Dk. (steel) } at the first convenient opportunity.

Cell DB 344' 1035 t. FPT 125 t. A.PT. 210 t.

FK. 7 BH. plt (cem.) Lloyds A YCP. P 49', B 113', F 38'

NOTED TRO 9 SEP 1958

he Certificate of Classification, to be endorsed
Cargo battens not fitted," and the same
notation to be printed in the Register Book.

AES 30.10.19

lr lfs 10/11/1919 It is concluded the record of "Cem." should be made in this case but the Surveyors should be requested to state if this is so.

© 2020 Lloyd's Register Foundation

003290-003297-0076

BEAMS, Bridge Deck, Angle, Bulb Angle, Tee, Tee Bulb, or Channel	9	22											
„ Angles on upper edge		26			26								
„ Spacing													
BEAMS, Forecastle Deck, Angle, Bulb Angle,	9	3½	46	9	3½	46							
„ Angle on ditto													
„ Tie Plates													
„ Deck. Material and thickness													

Steel