Rpt. 9.

No. 3644 a.

REPORT OF SURVEY FOR REPAIRS, &c., OF ENGINES AND BOILERS

(Received at London Office 21 APR 1953)

Date of writing Report 20th March 19 53 When handed in at Local Office 19 Port of DJAKARTA.

No in Reg. Book. Survey held at Pasar Ikan (Djakarta) Date. First Survey 26th Febr. Last Survey 6th March 1953. (No. of Visits 4)

-- on the Machinery of the ~~Wood, Iron or~~ Steel m.s. TELOK VI".

Year. Month.

Tonnage { Gross -- / Net -- | Vessel built at Djakarta By whom Vereenigde Prauwen Veren When 1950 8

Nominal Horse Power -- | Engines made at By whom Crossley When 1950

No. of Main Boilers -- | Boilers, when made (Main) -- (Donkey) --

No. of Donkey Boilers -- | Owners Swan Liong N.V. Owners' Address Djakarta. (if not already recorded in Appendix to Register Book.)

Steam Pressure— in Main Boilers -- | Managers Port Voyage

in Donkey Boilers -- | If Surveyed Afloat or in Dry Dock afloat and in drydock (State name of Dock.) V.P.V. Drydock

Last Report No. Port

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. ✠ for Special Survey. Date of last Survey and of Periodical Surveys.	Years assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any)

Particulars of Examination and Repairs (if any) General Examination

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined --

Was a damage report made by anyone else? If so, by whom? --

Did the Surveyor personally go inside each Main Boiler separately and make a through examination at this time? --

" " Donkey " " " --

If not, state for what reasons -- What parts of the Boilers could not be thus thoroughly examined? --

What special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? --

State latest date of internal examination of each boiler -- Present condition of funnel(s) Good

Did the Surveyor examine the Safety Valves of the Main Boilers? -- To what pressure were they afterwards adjusted under steam? --

Did the Surveyor examine the Safety Valves of the Donkey Boilers? -- To what pressure were they afterwards adjusted under steam? --

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers? --, and of the Donkey Boilers? --

Did the Surveyor examine the drain plugs of the Main Boilers? --, and of the Donkey Boilers? --

Did the Surveyor examine all the mountings of the Main Boilers? --, and of the Donkey Boilers? --

Has the screw shaft now been drawn and examined? Yes Has it a continuous liner? No Is an approved oil retaining appliance fitted at the after end? Yes

If shaft now been changed? No If so, state reasons -- Has the shaft now fitted been previously used? -- Has it a continuous liner? --

Is an approved oil retaining appliance fitted at the after end? -- State date of examination of Screw Shaft 27-2-'53. State the wear down in the stern bush A fit Is electric light and/or ~~power~~ fitted? Yes If so, did the Surveyor examine the generators, motors, switchgear, cables and fuses? Yes

Was the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? Yes

Engine parts, when referred to by numbers, should be counted from forward. Auxiliary machinery should be referred to by position in Machinery Space.

If the Survey is not complete, state what arrangements have been made for its completion and what remains to be done General Examination completed.

Owners requested for Classification in the Society's Register. A general examination while in dry-dock and afloat has been carried out. Vessel placed in drydock; propeller, sterntube and outside fastenings examined. Propeller having got too thin by cavitation a new bronze Lips propeller has been fitted. Tailshaft drawn and examined, fitting in propeller verified and all in order.
Shaftconnections opened out, examined and good. Main - and auxiliary engines completely opened out, all working parts examined and found in order. Main engine driven-and independent pumps opened out examined and in order. Compressors opened out, all working parts examined and good. Airreceivers opened out, cleaned, examined and in order.
Electric equipment meggertested, examined and good.
Main-and auxiliary machinery and all pumps tried under working condition and found satisfactory.
Having been away from Djakarta Mr. Waakop Reyers carried out part of the above survey.

General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, BS 9,11, B&MS 9,11, ✠LMC 9,11 or ✠LMC 140 lb., FD, &c.)

CS 3,34

The machinery being in order I am of opinion that pending approval of plans and full examination the notation of Classification contemplated may be given.

Survey Fee (per Section 29) £ 220,--

Special Damage or Repair Fee (if any) (per Section 29.) £ : :

Travelling expenses (if chargeable) £ : :

Fees applied for 20-3 1953

Received by me, 19

Committee's Minute TUES. 12 MAY 1953

Assigned Defered Noted

John F. Summers

Engineer Surveyor to Lloyd's Register of Shipping.

(Mr. WAAKOP REYERS).

Insert Character of Ship and Machinery precisely as in the Register Book.

Is a Certificate required? If so, to be sent to

© 2021 Lloyd's Register Foundation