F.E.

...ef Ship Surveyor **13.6.18**   Received from Chief Ship Surveyor _____

...AME Steel Twin S/S 'Duquesa'   Rpt. Hpl   No. 15499
                                                         mdb   9672

...rks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

...erse No. **91.37**   Depth "d"   **11.45**

...g: Table No. **3**   page **13**   Description Bulb angle as approved.

...udinal No. **39516**

Proportions $\dfrac{Length}{Depth}$ = 9.3

RETAIN

...heerstrake as approved.

... to damage caused whilst launching the vessel was examined in
...ck at Middlesbrough in March 1917. one shell plate renewed, 9 frames
...oors partly renewed, outer intercostals in way removed & continuous girder fitted,
...e plates. 6 frames & 3 floors repaired & minor repairs effected.
...dge anchor is 21 lbs lighter than required but it is submitted this might be
...d.

... This vessel appears to have been built in accordance with the

...nd the approved plans, and it is submitted she is eligible to

...sed ÷ 100 A1 (Steel) Shelter deck with freeboard," as

...nded. The Summer + Winter freeboard of 9'' 4½ from centre of disc

...of statutory deck line at Shelter deck, now marked on the

...s sides, to be inserted in the classification certificate, and

...d in the Register Book, and further, the remaining freeboards,

...n on the accompanying verification form to be inserted in the

...cate of classification.

...00 A1 (Steel) Shelter deck with freeboard.
...3 DKs (SH) + Shelter deck (SH - ws)
...Cell DB 362' 1121t. FPT 94t. APT 129t.
...F.K. 7 BH. Cem. Lloyds A & CP. B 257' + F 37' on shelter Dk.

...Date of Build

13.6.18

W383-0102