hat special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of these parts of each Boiler?

ate latest date of internal examination of each boiler

What parts of the Boilers could not be thus thoroughly examined?

f the Surveyor examine the Safety Valves of the Main Boilers?

To what pressure were they afterwards adjusted under

Present condition of funnel

usted under

onkey Boiler

onkey Boiler

onkey Boiler

Has it

Appliance fit

elivery Spa

ers, switchgea

Well cells 22" long x 6 5/8" wide x 15" high.

Box dimensions
7' 4" x 2' 6" x 5' 0"
say 10 cells per shelf.



88
6 3/4
23 3/4

Shelf area = 2640 sq ins
Area occupied by cells = 1460 sq ins
= 55%

22 x 6.625 x 10 = 1460 sq ins



fibre with a door in front and pipe work enough at its top to give 9'-0" top from the floor level, and at the back, side of compartment there is a 4" dia. vent pipe commencing 2'-0" from the floor and at the back side of the compartment there is a door with door catch to open and close for a

© 2020
Lloyd's Register Foundation
00265 002173-0046