25541

REPORT of SURVEY for REPAIRS.

Re July 6

No. 3403 Survey held at London Date 16th May & July 6 1863

on the Ship "Windsor Castle" Master W. Price

Tonnage 1074 Built at Sunderland When built 1857

By whom built _____ Owners Green &

Port belonging to London Destined Voyage _____

If Surveyed Afloat or in Dry Dock Green's Dry Dock & E. I. Dock

Last Survey, No. 24774 **Port** London. **Classed** 13 A.1 6.62

REPAIRS now done.

waterway seams of upper and lower decks caulked, also the butts of the topsides and upper deck; a 2" plank let in over poop waterway seam. 1 new Stark Hawse pipe, new windlass, new fore mast, and 2 bolts renewed in a Standard knee.

Present Condition of the

Decks	good	Treenails	good	Windlass and Capstan	good
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	and
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	seen	Ditto Ditto at other places	seen	Sails	sufficient
Planksheers		Keelsons		Anchors No. of	
Sheerstrakes		Clamps and Shelfs		Cables	
Topsides		Ceiling		Hawsers and Warps	
Wales		Rudder		Standing & Running Rigging	
Plank (Bottom) and Counter		Copper When put on			

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. good where seen

The ship is now in good and efficient condition and eligible in my opinion to remain as classed. A. 1.

The Amount of Fee.....£ : : *is received by me,*

Special..... : :

Certificate (if required) : :

Committee's Minute 10th July 18 63

Character assigned 13 A 1

J. Pearce.

© 2021 Lloyd's Register Foundation
LON667-0229