26955

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. 196 **No.** ____ Survey held at London Date 28th July to 3rd Aug.st 18 65.-

on the Ship "Mermaid" Master Henry Rose.-

Tonnage 1321 / 1223 Built at St Johns N.B. When built 1853

By whom built ____ Owners Wilson & Co.

Port belonging to Liverpool Destined Voyage New Zealand.

If Surveyed Afloat or in Dry Dock Ratcliff Cross Dry Dock.-

Last Survey, No. 25786 Port London. Classed 7.A.1. 63

Rest 63- 5 yrs.

REPAIRS

Now done:-

Stripped the yellow metal off the Bottom, and caulked from Keel to Wood-sheathing.-

Resheathed the Bottom with yellow metal on felt,- and renewed the Starboard Main Channel with American Elm.-

Present Condition of the

Decks	good	Treenails	good	Windlass and Capstan	good
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings	fine	Timbers of the Frame at the openings	where	Masts, Yards, &c. By inquiry and observation from the deck.-	and
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Sails	sufficient
Planksheers	where	Keelsons		Anchors No. of	
Sheerstrakes	painted	Clamps and Shelfs	seen.-	Cables	where
Topsides	seen.-	Ceiling		Hawsers and Warps	
Wales		Rudder			seen.-
Plank (Bottom) and Counter	caulked.	Copper F. & M. When put on	now	Standing & Running Rigging	

General Observations and Opinion, *Caulking of Bottom, Deck, & Waterways.* Good where tested.-

She is now in good and efficient condition, and fit, in our opinion, to remain as Classed.-

James Williamson.-

The Amount of Fee.....£ —:—:— is received by me,

Special..... 1:1:0

Certificate (if required) —:—:—

Committee's Minute 25th August 18 65

Character assigned Rest 5 Yrs 1

© 2021 Lloyd's Register Foundation
LON 650-0054