No. 55234

Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office 2/3/94)

Date of writing Report 2.3.94 18 When handed in at Local Office 18 Port of London

No. in Reg. Book. 119 Survey held at London Date, First Survey + Last Survey Mar: 1 1894 (No. of Visits 1)

on the Machinery of the ~~Wood~~, Iron ~~or Steel~~ S. S. "Deerhound" Master

Tonnage	Gross 443	Vessel built at London	By whom Forrest & Son
	Net 271		When 1882 - 10 (YEAR. MONTH.)
Registered Horse Power	70	Engines made at Gls:	When 1882 Boilers, when made (Main) 1882 (Donkey)
No. of Main Boilers	1	Owners Walker, Howard & Co	Port London Voyage
Steam Pressure in Main Boilers	80lbs	If Surveyed Afloat ~~or in Dry Dock~~ (State name of Dock.)	River
in Donkey Boiler			

Last Survey No. 55139 Port Lon

Particulars of Classification *(which must be inserted precisely as in Register Book & Supplements).*

CHARACTER. ✠ for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned now expired.	Machinery and Boiler Surveys (including date of N.B., if any).
+100 A1		+LMC. 7.91
5.93		B.S. 9.92.
SS. Lon: No 2 - 91		

Particulars of Examination and Repairs (if any)

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

Do. " Donkey " " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

At what pressure were they afterwards adjusted under steam?

Did the Surveyor examine the Safety Valves of Donkey Boiler?

To what pressure were they afterwards adjusted?

If the Survey is not complete state what arrangements have been made for its completion?

Examined temporary false valve face on H. P. cylinder, which has now been renewed in order to allow the vessel to make another voyage say for ten days when a new H. P. cylinder will be fitted, I say in about ten days.

In my opinion this vessel should not be allowed to proceed to sea, after this voyage, until the new H. P. cylr. has been fitted.

General Observations, Opinion, and Recommendation:— As far as seen this vessel

(State clearly what alteration, if any, is suggested to be made in the existing classification and notification of the vessel's machinery in the Register Book, consequent upon this survey: thus, for example, B.S. 9,92, B.&M.S. 9,92 or ✠L.M.C. 9,92, as the case may be.)

appears eligible to remain as classed subject to a new H. P. cylr: being fitted on completion of this voy: only - say in 10 days. & the remdr of B.S. as per Lon. Rpt: No 55039 herewith.

Office or Registration Fee (per Sec. 27)	£	:	:
Survey Fee (per Section 28)	£	✓	: ✓ :
Special Damage Fee (per Section 28)	£	:	:
Travelling Expenses (if chargeable)	£	:	:

Fees applied for ..... 18 .....

Received by me, ... 18 .....

Geo: E. Wilkinson.
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

*State if Certificate is required

Committee's Minute TUES. 6 MAR 1894

Assigned Deferred for complr. of

Wrote Owrs BS &c. Lr. 6.3.94

FRI 13 APL 1894

*Certificate to be sent to

*Note if a Report is also now sent on the Ship or if not whether, and when, one will be sent.

Insert Character of Ship and Machinery precisely as in the Register Book.

16—LRPH—Form No. 9—Transfer Ink 5,000, 2/10/93.

(The Surveyors are requested not to write on or below the space for Committee's Minute.)

© 2019 Lloyd's Register Foundation
LON701-0298