Less Crew Space 26 · 96
Less above Crown of Engine Room .. 10 · 30
FOR FEES .. 246 · 38

Length on deck from after part of stem to fore part of stern post 132 · 16

2nd Number 5978

Owners

Managers (Where necessary to be entered in Reg. Book).

(3m,4,5.)

Received by Chief Ship Surveyor 19. 12. 05

Received from Chief Ship Surveyor

VESSEL'S NAME Sct. Steam Trawler "Chieftain" Report Hull No. 17419

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report*, 24/5/92.)

Nature of Survey First entry

It is submitted the Hull Surveyors be informed that as the new stockless ~~[illegible]~~ anchor is to be placed on board the Vessel on her return to their port in about three weeks time, and ~~the~~ classification will be deferred until that has been done.

Sr. Hull 19/12/05

C. R. 19/12/05

© 2019 Lloyd's Register Foundation

W1218-0035

" " " "