REPORT ON BOILERS.

No. 1005-1.

Received at London Office TUE. 12 MAR. 1918

Reporting Report 191 When handed in at Local Office 11.3.18 191 Port of Middlesbrough

Survey held at Stockton-on-Tees Date, First Survey Last Survey 191

(Number of Visits)

ok. on the Ferro-Concrete S/s "Armistice" Tons { Gross / Net

Built at Barrow-in-Furness By whom built Ferro-Concrete Ship Construction Co. When built 1919

made at S. Shields By whom made G. T. Grey & Co Ltd. When made

made at Stockton By whom made Messrs Riley Bros Ltd (No 5103) When made 1918

ed Horse Power Owners The Ferro-Concrete Ship Construction Co Ltd. (Leopold Walford (London) Ltd Mngrs.) Port belonging to London

TITUBULAR BOILERS—MAIN, AUXILIARY OR DONKEY.—*Manufacturers of Steel* John Spencer & Sons David Colville & Sons

for record (S) **Total Heating Surface of Boilers** 743 ☐' Is forced draft fitted No **No. and Description of**

One single ended **Working Pressure** 140 Tested by hydraulic pressure to 280 Date of test 4.3.18

Certificate 5872 Can each boiler be worked separately Yes. **Area of fire grate in each boiler** 29 ☐' No. and Description of

valves to each boiler Two - Spring-loaded Area of each valve 3.98 ☐" Pressure to which they are adjusted 143 lbs per ☐"

y fitted with easing gear Yes In case of donkey boilers, state whether steam from main boilers can enter the donkey boiler ✓

st distance between boilers or uptakes and bunkers or woodwork 4'-0" ~~Mean~~ Inside dia. of boilers 9'-6" Length 9'-0"

al of shell plates Steel Thickness 43/64 Range of tensile strength 28-32 Are the shell plates welded or flanged no

p. of riveting: cir. seams 2 R. lap long. seams 2 R - 2 Rivets 3 Rivets per pitch Diameter of rivet holes in long. seams 15/16 Pitch of rivets 5½"

~~plates or~~ width of butt straps 9" × 1 1/16" Per centages of strength of longitudinal joint rivets 83.7 plate 82.9 Working pressure of shell by

24-1-140 Size of manhole in shell 19" × 15" Size of compensating ring 7" × 1" Mc Neil **No. and Description of Furnaces in each**

-19,7- 2 plain Material steel Outside diameter 36" Length of plain part top 66¾ bottom 92 Thickness of plates crown 5/8 bottom 4/16 mean

S.V. 3/8" ption of longitudinal joint Weld No. of strengthening rings none Working pressure of furnace by the rules 153 Combustion chamber

o. 2 S. Material Steel Thickness: Sides 9/16" Back 9/16" Top 9/16" Bottom 3/4" Pitch of stays to ditto: Sides 9" × 8" Back 9" × 8¼"

o. 2 S. 2 × 8" If stays are fitted with nuts or riveted heads nuts Working pressure by rules 140 Material of stays steel Area at

st part 1.45 Area supported by each stay 74.25 Working pressure by rules 156 End plates in steam space: Material steel Thickness 7/8"

of stays 14 / 17 × 16½ to screw stays / 15½ How are stays secured nuts & 6 × ½ washers Working pressure by rules 140 Material of stays steel Area at smallest part 4.11

supported by each stay 278 Working pressure by rules 154 Material of Front plates at bottom steel Thickness 7/8" Material of

back plate steel Thickness 7/8" Greatest pitch of stays 13¼ × 8¼ Working pressure of plate by rules 216 Diameter of tubes 3¼"

of tubes 4½" × 4¼" Material of tube plates steel Thickness: Front 7/8" Back 5/8" Mean pitch of stays 10" Pitch across wide

spaces 13¼" Working pressures by rules 140 Girders to Chamber tops: Material steel Depth and thickness of

at centre 7" × 1¼" Length as per rule 26 Distance apart 9½" Number and pitch of Stays in each 2 @ 8"

g pressure by rules 146 Steam dome: ~~description of joint to shell~~ none % of strength of joint

er Thickness of shell plates Material Description of longitudinal joint Diam. of rivet holes

f rivets Working pressure of shell by rules Crown plates Thickness How stayed

RHEATER. ~~Type~~ none Date of Approval of Plan Tested by Hydraulic Pressure to

Test Is a Safety Valve fitted to each Section of the Superheater which can be shut off from the Boiler

of Safety Valve Pressure to which each is adjusted Is Easing Gear fitted

VEY REQUEST
S. 1407 ATTACHED.

FOR RILEY BROS. (BOILER MAKERS) LIMITED
SECRETARY.

The foregoing is a correct description,

Manufacturer.

During progress of work in shops: 1917. Nov 14.19.23. Dec 10.20. 1918. Jan 10.23 Is the approved plan of boiler forwarded herewith yes

During erection on board vessel: 1918. Feb 20.28. Mar 4 1919, Jan 3 9th 13th 17th 21st 24th 28th, 30th Feb 3rd 5th 6th 7th Total No. of visits 12. Total 23.

Total 11

ERAL REMARKS (*State quality of workmanship, opinions as to class, &c.*) This boiler has been built under
ial Survey: is of good material and workmanship and on completion was tested by hydraulic
sure with satisfactory results. The boiler has been forwarded to South Shields
, boiler has been efficiently fitted on board; its safety valves have been adjusted
r steam as noted above, & it was found tight under a full head of steam

John Houston
15/2/19

vey Fee ... ... £ 2-10-0 When applied for, Monthly A/C

velling Expenses (if any) £ : : When received, 191

W^m Morrison & Jas Shorts
Engineer Surveyor to Lloyd's Register of Shipping.

mmittee's Minute FRI. - 7 MAR. 1919

igned

Lloyd's Register Foundation