COPY

Lloyd's Register of Shipping.

9, OURA (KAIGAN-DORI)

NAGASAKI.

21st November 1934.

CERTIFICATE No.1115.

This is to Certify that

at the request of Messrs.Mitsubishi Denki Kaisha,Ltd., Nagasaki, attend at their works, on the 5th November 1934, for the purpose of examining under test of the following Switchboards, intended for Vessel No.594, now being built by Messrs.Mitsubishi Jukogyo Kaisha,Ltd., Nagasaki.

One Complete Main Switchboard, No.62104 consisting of followings:-

Four panels for 80 K.W.Main Generators.
Two panels for Motors.
Two panels for Lighting.

One Complete Emergency Switchboard, No.62106 consisting of followings:-

Two panels for 8 K.W.Emergency Generators.
Two panels for Wireless Telegraph & Lighting.

A heigh voltage test of 2000 volts A.C.was applied to all panels for one minute, and insulation test, temperature rise test under continuous current & calibration tests were carried out as detailed below, and all found satisfactory.

Two circuit breakers on 80 K.W.Main Generator Panel.

Continuous current of 730 amps at 110 volts for 5 hours.
" " " 920 " " " " " 2 " .
Calibration tests at 1120.1360 & 1600 amps for Overload Relay.
" " " 40. 80 & 200 amps for Reverse Current Relay.

One circuit breaker on 8 K.W.Emergency Generator Panel.

Continuous current of 73 amps at 110 volts for 5 hours.
" " " 92 " " " " " 2 " .
Calibration tests at 73. 110 & 145 amps for Overload Relay.

For the purpose of identification the name plates have been stamped as follows:-

Main Switchboard.	Emergency Switchboard.
LLOYD'S No.1115. TK. 5-11-34	LLOYD'S No.1115-A. TK. 5-11-34

T. Kunishi

ASSIST. SURVEYOR TO LLOYD'S REGISTER.

Fee Yen 75:00

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society.

© 2021 Lloyd's Register Foundation
W1340-0042