Engine Room .. } 195·07
Tonnage for Fees..

Proportions—Depths to Length—Upper Deck Beam at side to top of keel } 9.38

Residence

250,12,10.

F.E.

Received by Chief Ship Surveyor 7/3/11

Received from Chief Ship Surveyor

VESSEL'S NAME M.L.S. "Berri" Rpt. Hul No. 23447

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report*, 24/5/92.)

Transverse No. 33.62 Depth "d" 10.92

Framing: Table No. 3 page 9 Description Angle angle, as approved

Longitudinal No. 3866

Proportions $\frac{\text{Length}}{\text{Depth}}$ = 9.38

MAIN Deck Sheerstrake ·56 in line of ·34 (not required)

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ✠ 100A1 (Hul) "Steam Trawler", as recommended.

✠ 100A1 (Hul) "Steam Trawler"

1 Dr

Bk 8" & B.H. Cem Lloyds 2066 Q 61

PLAN

7/3/11

© 2021 Lloyd's Register Foundation

W1390-0031

,,	Bulb Angle, Plate, Tee Bulb, or Channel Angles on upper edge		✓					,,	Tie Plates
								,,	Deck. Material and thickness