F.E.

...d by Chief Ship Surveyor 26. 10. 05 Received from Chief Ship Surveyor

...EL'S NAME Stt. Twin S.S. "Selta" Rpts { Rll. No. 5963 / Lm. - 67800

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report*, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	2/20"	Proportions
Spar Sheerstrake . .	✓	✓
Description of Framing:— (viz., ordinary, deep, zed, channel or bulb-angle).	Ordinary, but depth of girder increased to 8" to compensate for wider spacing.	

Close ceiling has been fitted under the hatchways and over the limbers only, and no solid cement has been laid on the inner surface of the shell plating in the cellular double bottom, as specified by the owners*. See correspondence with reference to the close ceiling attached.
The chain cables are 2 cwt. 3 qr. 16 lb. or 3/10 of one per cent less in weight than required by Table 22.

...ther respects This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ✠ 100 A 1 ("Steel").

✠ 100 A 1 ("Steel")

3 BRs (U Stt - WS pt Teak & 1 Stt - WS)

W. B= Cell DBs 83' w E & B 115' f 178' 1191t

F K & BK 3" 8BH pt Cem. Lloyd's A & CP P 96' B 182' F 103'

* The inside of the cellular double bottom to be ~~[illegible]~~ examined in such a way that each compartment comes under survey not less frequently than once a year, and the owners to be informed accordingly.

C. H. 26/10/05

5c,5,5. The Surveyor should be requested to state whether he called attention to the Chain Cables being 2 cwt. 3 qr. 16 lb. less in weight than required by Table 22, and why he did not direct the Committee's attention to the same in his report.

© 2021 Lloyd's Register Foundation

W1426-0064

| | | |