Urgent

s.s."INCHDAIRNIE". No.73838 in Register Book.

Mr. J.Fletcher, Owner of this vessel, called at this today and states that the vessel is at present at lam undergoing Special Survey No.2 on the hull and ery.

He says that the Rotterdam Surveyors have informed t the screwshaft should be drawn in for examination.

The screwshaft was examined in February of this year recorded in the Register Book with a"C.L.2,28".

IT IS SUBMITTED the Rotterdam Surveyors should be d by cable that the screwshaft was examined in February d it is therefore not necessary to re-examine it for the Survey No.2 now being carried out.

If there are any special reasons for recommending the o be drawn in for examination, particulars should be ed at once.

4.12.28

© 2019 Lloyd's Register Foundation

W482-0384